

Project No: TOL001052030201
Project: Bioremediation Pilot Study

Client: AFCEE

Location: Site 24 - Vandenberg AFB

Northing(ft): 2100136.6

Borehole ID: HGL68(24MW8A-2)

Date: 10/09/2003

Geologist: M. Jackson

Checked By: D. Smith, R.G.

Ground Surface Elevation(ft msl): 459.4

Easting(ft): 5801073.4

SUBSURFACE PROFILE						SAMPLE	<del></del>	T	
Depth	Symbol	Description	nscs	Elevation	Recovery %	Blow	PID (ppm)	Water Level	Remarks
2-		Sand and gravel	FL						
6				452	0	29/19/31			Pilot study monitoring
8 1		Clayey sand Pale yellowish brown with dark yellowish orange mottling, slightly moist, dense	SC SP	451					well installed in boring.
12-		Poorly graded sand Moderate yellowish brown, slightly moist, slightly dense			30	80 for 5"	1.9		
16					75	55/77	2.7		
18				439					
22		Clayey sand Pale yellowish brown, slightly moist, dense, medium grained sand	SC	436	60	31/80 for 6"	3.1		
24	44	Sandy clay	ĊL	435					
26-		Poorly graded sand Dark yellowish brown, very moist, slightly dense			100	87 for 6"	6.8		
28-		at 27.5' color change to light olive gray	SP						
30 - 1 32 - 1			J.		20	72/70 for 5"			
34		at 34' unit becomes slightly cemented at 35' unit very moist to saturated							
36 <del> </del> 38 <del> </del>		at 39.5' to 40' <u>Clayey Sand</u> - Moderate to dark yellowish brown, slightly moist to moist, very			50	60/65 for 6"	5.2		
40		dense	SC	419	70 70	49/90 50/60	10.4 3.4		

Drilled By: Layne Christensen

HydroGeoLogic, Inc.

Drill Method: Dual Tube

4600 Northgate Blvd., Suite 207 Sacramento, CA 95834

Drilling Equipment: AP 1000

(916) 614-8770 FAX (916) 614-8775

(212) 211 211 2 77 2 (010)

Boring Diameter: 10"

Total Depth Drilled: 39.0'

Sheet: 1 of 1

Sampling Equipment: 2" x 18" CA Mod Split Spoon